

EXAMPLE 1: Single VPLEX Engine & XtremIO X-Brick

FABRIC 'A' SCRIPT

Alias's for VPLEX Back-end ports#####

fcalias name VPLEX_E1_A1_FC00 vsan 10

member pwwn 50:00:14:42:xx:xx:xx:10

fcalias name VPLEX_E1_B1_FC00 vsan 10

member pwwn 50:00:14:42:xx:xx:xx:10

Alias's for XtremIO Front-end ports#####

fcalias name XtremIO-X1-SC1-FC1 vsan 10

member pwwn 21:00:00:24:xx:xx:xx:94

fcalias name XtremIO-X1-SC2-FC1 vsan 10

member pwwn 21:00:00:24:xx:xx:xx:02

Create ZONES

zone name Z_VPLEX_E1_A1_FC00-XtremIO-X1-SC1-FC1 vsan 10

member fcalias VPLEX_E1_A1_FC00

member fcalias XtremIO-X1-SC1-FC1

zone name Z_VPLEX_E1_B1_FC00-XtremIO-X1-SC2-FC1 vsan 10

member fcalias VPLEX_E1_B1_FC00

member fcalias XtremIO-X1-SC2-FC1

ZONESET

zoneset name vsan10_zs vsan 10

member Z_VPLEX_E1_A1_FC00-XtremIO-X1-SC1-FC1

member Z_VPLEX_E1_B1_FC00-XtremIO-X1-SC2-FC1

Activate & Commit

zoneset activate name vsan10_zs vsan 10

zone commit vsan 10

end

FABRIC 'B' SCRIPT

Alias's for VPLEX Back-end ports#####

fcalias name VPLEX_E1_A1_FC01 vsan 11

member pwwn 50:00:14:42:xx:xx:xx:11

fcalias name VPLEX_E1_B1_FC01 vsan 11

member pwwn 50:00:14:42:xx:xx:xx:11

Alias's for XtremIO Front-end ports#####

fcalias name XtremIO-X1-SC1-FC2 vsan 11

member pwwn 21:00:00:24:xx:xx:xx:95

fcalias name XtremIO-X1-SC2-FC2 vsan 11

member pwwn 21:00:00:24:xx:xx:xx:03

Create ZONES

zone name Z_VPLEX_E1_A1_FC01-XtremIO-X1-SC2-FC2 vsan 11

member fcalias VPLEX_E1_A1_FC01

member fcalias XtremIO-X1-SC2-FC2

zone name Z_VPLEX_E1_B1_FC01-XtremIO-X1-SC1-FC2 vsan 11

member fcalias VPLEX_E1_B1_FC01

member fcalias XtremIO-X1-SC1-FC2

ZONESET

zoneset name vsan11_zs vsan 11

member Z_VPLEX_E1_A1_FC01-XtremIO-X1-SC2-FC2

member Z_VPLEX_E1_B1_FC01-XtremIO-X1-SC1-FC2

Activate & Commit

zoneset activate name vsan11_zs vsan 11

zone commit vsan 11

end